0023

From:

Karl Houskeeper

To:

dshaver@coalsource.com

CC:

Angela Nance; Daron Haddock; Suzanne Steab

Date:

7/9/2009 3:26 PM

Subject:

June 2009 Inspection Reports

Attachments: Centennial June 2009.pdf; Crandall June 2009.pdf

Dave,

Attached is the June 2009 inspection reports for Centennial and Crandall.

Thanks

Karl

0 wtepono C0070019

Œ



State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director

Permitee: ANDALEX RESOURCES INC TOWER DIVISION

Operator: ANDALEX RESOURCES INC TOWER DIVISION

JON M. HUNTSMAN, JR. Governor GARY R. HERBERT Lieutenant Governor

Site: CENTENNIAL MINE Address: 6750 AIRPORT RD, PO BOX 902 PRICE UT 84501

Representatives Present During the Inspection: Company David Shaver Manager

OGM Karl Houskeeper Environmental Scientist III

County: CARBON

Total Disturbed

Phase I

Phase II

Phase III

Permit Type: PERMANENT COAL PROGRAM Permit Status: ACTIVE

Current Acreages

47.19

6,516.91 Total Permitted

✓ State ☐ County

✓ Fee ☐ Other

Inspection Report

Permit Number:	C0070019
Inspection Type:	PARTIAL
Inspection Date:	Wednesday, June 03, 2009
Start Date/Time:	6/3/2009 7:30:00 AM
End Date/Time:	6/3/2009 10:30:00 AM
Last Inspection:	Wednesday, March 11, 2009

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, Temp. 67 Deg. F. InspectionID Report Number: 2025

Accepted by: jhelfric

6/4/2009

Types of Operations Mineral Ownership ✓ Federal ✓ Underground

> ☐ Surface ☐ Loadout Processing Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

inspector's	Signature:

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Date

Wednesday, June 03, 2009

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070019 Inspection Type: PARTIAL

Inspection Date: Wednesday, June 03, 2009

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	V		✓	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	✓		V	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste	V		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other	V	П	7	П

Inspection Continuation Sheet

Permit Number: C0070019
Inspection Type: PARTIAL

Inspection Date: Wednesday, June 03, 2009

Page 3 of 3

2. Signs and Markers

The mine permit ID signs are located at the contact points of public access to the permit area.

4.a Hydrologic Balance: Diversions

The brattice that was in disturbed diversions DD-11 and DD-2. DD-11 from the previous inspection has been removed.

The culvert outlet by the main bathhouse is has been repaired.

8. Noncoal Waste

The garbage can was still in the abandoned sediment pond from the previous inspection, but was removed during the current inspection.

22. Other

The dried weeds that were observed during the prior inspection around the fuel storage area have been cleaned up and removed.